

Item Photograph Perumal, Wrathall & Murphy Pty. Ltd. for Dungog BW2/16A17 for Dungog Shire Council A21 in association with Cameron McNamara Heritage Council of NSW C2/10,11 Location .5km north of Wirragulla opposite entrance to Precinct Crooks Park station on the main road south of Dungog Date 17/1/87 Title Description Wirragulla pumping station and pipe Survey By AB Description Orange brick pumping station with cream painted concrete base and middle section. The water pipe passes to the rear of the building. The sign on the front of the building says "HDWS&S Board Wirragulla Boosting Station" History: Significance: Local Alterations/Integrity: Condition: Style: Street Context: ☐ Good ☐ Fair ☐Positive contribution ☐ Poor Period: ☐ Neutral ☐ Pre-1890 ☐ 1915-45 ☐ Out of Character □ 1890-1915 □ 1945-Possible remedies Current Use: Original use: Pumping station Actual date (if known) Current listings: \square AHC \square HC \square NT ☐ RAIA/Other Thematic context Services References: Nil


Existence on Early Plans, Maps or Drawings Shown on Early Photographs Location Map Sketch



DUNGOG HERITA Perumal, Wrathall & Murphy Pty. I in association with Cameron McNa	AGE STUDY Ltd. for Dungog Shire Counci mara Heritage Council of NSW]	Item A22	Photograph BW 2/26A C Nil
Location Just north of Vasy, over the Paterson River. Precinct Date 17/1/87				
Title Description Vacy bridge Survey By AB				
Description High level timber truss	bridge built in 1898 over	the	Paterson I	River.
History:				
Significance: Regional and local				
Alterations/Integrity:				
Condition:	Style:	Stree	t Context:	
☐ Fair ☐ Poor	Period: ☐ Pre-1890 ☐ 1915-45	□N	ositive contribut	
Current Use: Original use: Bridge	☐ 1890-1915 ☐ 1945- Actual date 18 98 (if known)	1	ut of Character	
Current listings: AHC HC RAIA/Other		e (de sizo	Own H	
Thematic context Transport				O. Marie
References: Thematic History: 97; 105				
*				




DUNGOG HERITA Perumal, Wrathall & Murphy Pty. in association with Cameron McNa	AGE S Ltd. mara	TUDY for Dungog Shire Heritage Council	e Council of NSW	Item AQ3	Photograph BW 1/6 C 1/7
Location 3/4 km fron East	Gresfo	rd		Precinct	
Title Description Camyr Allyr	n Bridge			Date 15/1 Survey By	
Description Low level timber bridge					
History:					
Significance: State and regi	onal.				
Alterations/Integrity:					
Condition: Good	Style:		St	reet Context:	
☐ Fair ☐ Poor	Period:	?		Positive contribu	
Current Use: bridge Original use:		1915 🗹 1945- ?	Po	Out of Characte	
Current listings: AHC HC RAIA/Other					, ide a disc
Thematic context Transfort			fire fra		
References:					4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
*					



Item Photograph DUNGOG HERITAGE STUDY Perumal, Wrathall & Murphy Pty. Ltd. for Dungog BW 1/7-9 for Dungog Shire Council C 1/8 in association with Cameron McNamara Heritage Council of NSW Location Next to St. Anne's Church of England church Gresford. At the end of Durham Road. Our Pathusan R Precinct Date 15/1/87 Title Description Vehicle suspension bridge Gresford Survey By AB Description Next to St. Anne's church. Trestle type vehicle and/or footbridge. Suspended on steel cables. Wide enough for one car at a time to cross. History: Significance: Regional and local Alterations/Integrity: Condition: Style: Street Context: Good ☐ Fair Positive contribution ☐ Poor Period: / ☐ Neutral ☐ Pre-1890 ☐ 1915-45 Out of Character □ 1890-1915 □ 1945-Possible remedies Current Use: Bridge Bridge Original use: Actual date (if known) Current listings: \square AHC \square HC \square NT ☐ RAIA/Other Thematic context Transport References:


	•
	Item
Existence on Early Plans, Maps or Drawings	Architect Builder
	Original Owner
Shown on Early Photographs	
Location Map Sketch	


-,



GresFORD 1:25,000


;		· ,			
DUNGOG HERITA Perumal, Wrathall & Murphy Pty. I in association with Cameron McNa	Ltd. for Dungog Shire Council		Item	Photograph BW 1/11 C 1/11	
Location Allynbrook. St. Mary's Bridge. Over Allyn River. Remains only, as was replaced by a new bridge in 1970. Title Description Remains of first St. Mary's bridge over Survey ByAB					
stone remains on western end.	A st bridge. Timber and conc n side of new bridge. Dum	Allyn crete np of	base with stones on	dump of northern	
	ge over the Allyn River at	_			
Significance: Local					
Alterations/Integrity: Only remains next to the	e new bridge				
Condition: Good Fair Poor	Style: Period: ?	□Pos □ Ne			
Current Use: Nil Original use:Bridge	☐ Pre-1890 ☐ 1915-45 ☐ 1890-1915 ☐ 1945- Actual date(if known)		nt of Character		
Current listings: AHC HC RAIA/Other					
Thematic context Transport					
References: Thematic History 91-2 and 105					






DUNGOG HERITA Perumal, Wrathall & Murphy Pty. I in association with Cameron McNa	Ltd. for Dungog Shire Counci	1	Item A26	Photograph Nil
Diamada	ester River just south of potbridge marked on Chiche	:	Date 16/1	
Title Description Survey by AB				
Description Map 1km south of Chichester. This bridge no longer exists, but was washed away by the floods a few years ago. (This information was provided by a local man who we interviewed at Chichester) History:				
Significance:				
Alterations/Integrity:				
Condition: Good Fair	Style:	_	t Context:	ion
Poor	Period:	ַ אַ	eutral	
Current Use: Original use:	☐ Pre-1890 ☐ 1915-45 ☐ 1890-1915 ☐ 1945- Actual date		ut of Character	
Current listings: AHC HC RAIA/Other				
Thematic context				
References:				


.




				<u> </u>
DUNGOG HERITA	AGE STUDY		Item	Photograph
Perumal, Wrathall & Murphy Pty. in association with Cameron McNa	Ltd. for Dungog Shire Council	i	A27	BW 1/35 C 1/33
Location Salisbury. About over the Willbims River.		Precinct Date 16/1/87		
Title Description Footbridge	e over Williams River at		Survey By	
Description	Salisbury.		Burtoy By	
<u>-</u>	ver Williams River, behind	l the	chorch	about
History:				
Significance: Regional and local				
Alterations/Integrity:				
The same and the greek.				
				j
Condition:	Style:		t Context:	
☐ Fair ☐ Poor	Period:		sitive contribu eutral	tion
	☐ Pre-1890 ☐ 1915-45		ut of Character	.
Current Use: Original use: Footbridge	□ 1890-1915 □ 1945-	Possi	ble remedies	
Original use:	Actual date(if known)	********	•••••	
Current listings:	- LO			
□ АНС □ НС		. ***	· ,	
□ NT □ RAIA/Other	7.			
Thematic context		٠	. (b)	4.
Transport				
-	Na was n		· · · · · · · · · · · · · · · · · · ·	100
References:	The second secon			
Nil			Vicinity of	
		21 - 22 M 18 - 23 - 24		and the second
	Web.			
*	· MIL is a second of the secon			



Item Photograph DUNGOG HERITAGE STUDY Perumal, Wrathall & Murphy Pty. Ltd. BW 2/9A,1(A for Dungog Shire Council in association with Cameron McNamara Heritage Council of NSW C 2/7 Suspension from the road across the Allyn Location Precinct River to "Allyn Vale" Date 16/1/87 Title Description Suspension footbridge over the Allyn Survey By AB Description River about 1.5km north of Eccleston to the west of the road. Flimsy suspension footbridge of steel cables beneath wooden boards. Barred gate with sign above "Private property intruders out". History: Significance: Regional and local Alterations/Integrity: Barred gate on the eastern side of the footbridge Condition: Style: Street Context: ☐ Good Fair Positive contribution ₩ Poor Period: ☐ Neutral ☐ Pre-1890 ☐ 1915-45 ☐ Out of Character ☐ 1890-1915 ☐ 1945-Current Use: Possible remedies Original use: Footbridge Actual date (if known) Current listings: \square AHC \square HC \square NT ☐ RAIA/Other Thematic context Transport References: Nil






DUNGOG HERITA Perumal, Wrathall & Murphy Pty. in association with Cameron McNa	Ltd. for Dungog Shire Counci	1	Item A29	Photograph BW 2/8A C 2/6	
north of Eccleston to the causeway over the Allyn	ge (to take cars) about 4. he the west of the first River(going north). bridge over Allyn River	5km	Precinct Date 16/1 Survey By		
Description Suspension bridge big enough to take a car, over the Allyn River north of Eccleston. This is c. 8km south of Upper Allyn.					
History:					
Significance:					
Regional and local					
Alterations/Integrity:					
Condition: Good Fair	Style:	1/	et Context:	tion	
Poor	Period:		eutral	11011	
Current Use: Original use: Suspension bridge	☐ Pre-1890 ☐ 1915-45 ☐ 1890-1915 ☐ 1945- Actual date(if known)	Poss	-		
Current listings: AHC HC RAIA/Other	<u>;</u> 6			·	
Thematic context Transport					
References:					
*				***	

CHICHESTER 1:25,000

DUNGOG HERITA Perumal, Wrathall & Murphy Pty. in association with Cameron McNa	AGE STUDY Ltd. for Dungog Shire Counci mara Heritage Council of NSW	il V	Item A30	Photograph BW 2/29A C 2/29	
Location Over Paterson R	iver at "Gostwyck"		Precinct Date 17/1/87		
Title Description Gostwyck b	ridge		Survey By		
Description					
Road bridge high over t	he Paterson River at "Gos	twyck"	•		
History:					
Opened in 1878					
0,					
Significance: Regional and local					
Regional and local					
Alterations/Integrity:					
Condition:	Style:	Street	Context:		
☑ Good □ Fair		Проч	sitive contribu	tion	
□ Poor	Period:	☐ Ne		VIO.1.	
Current Use:	☐ Pre-1890 ☐ 1915-45	i	it of Characte ble remedies		
Original use: Bridge	☐ 1890-1915 ☐ 1945- Actual date/8 98	POSSII	oie remedies		
· · · · · · · · · · · · · · · · · · ·	(if known)				
Current listings:		in.	y s		
☐ AHC ☐ HC ☐ NT ☐ RAIA/Other					
Thematic context					
Transport	34 美国				
-					
References:					
Thematic History					
: 104; 133				**************************************	
				Andrew Comment	
			ACAMINI (F. 1)	A STATE	
*		对外 分类		en de la companya de La companya de la co	



DUNGOG HERITA Perumal, Wrathall & Murphy Pty. I in association with Cameron McNai	AGE STUDY Ltd. for Dungog Shire Council mara Heritage Council of NSW		Item ASI	Photograph	
Location Extension of Pri Paterson Title Description Queen's Wh	nces St near Tucker Park, narf		Precinct Date Survey By		
Description Mentioned in the Thematic History: 100. This was not found. A local man told me that the remains were there about 30 years ago, but it is not visible now. It was at the end of the extension of Prince Street, now in Tucker Park. History:					
Significance:					
Alterations/Integrity:					
Condition: Good Fair Poor	Style: Period:	□Ро	et Context: ositive contribut	tion	
Current Use: Original use:	☐ Pre-1890 ☐ 1915-45 ☐ 1890-1915 ☐ 1945- Actual date(if known)	☐ Neutral ☐ Out of Character Possible remedies			
Current listings: AHC HC NT RAIA/Other					
Thematic context					
References:					

÷ ,

				·	
DUNGOG HERITA Perumal, Wrathall & Murphy Pty. I in association with Cameron McNar	AGE STUDY Ltd. for Dungog Shire Coun mara Heritage Council of NS	cil W	Item A32	Photograph BW 3/15 C 3/8	
Location Clarence Town. Bridge over Williams River North eastern part of the town. Title Description Bridge over the Williams River, Clarence Precinct Date 17/1/87 Survey By AB					
Description Town. Oldest known timber truss bridge in the care of the NSW DMR.					
History: Built in 1878. Repaired in 1927 and 1974. Two timber truss spans each 100 feet long. (See NT Listing Proposal for details)					
Significance: State and regional					
Alterations/Integrity: Repaired in 1927 in the	original style				
Condition: Good Fair	Style:		et Context:	ion	
☐ Poor	Period:	□ и □ о	eutral ut of Character		
Current Use: Bridge Original use:	口 1890-1915 口 1945- Actual date(if known)	Possi	ible remedies		
Current listings: AHC HC NT RAIA/Other					
Thematic context Transport					
References: Thematic History:104.					
NT Listing Proposal					

= .

Existence on Early Plans, Maps or Drawings Shown on Early Photographs Location Map Sketch

and the constituent with a single property of the single property of		=
CLARENCETOWN	CLARENCETOWN BRIDGE	William River immediately east of Clarencetown
(Town or District)		
Post Code 2321 Dungog Local Govt Area Shire Counci	1	
Author of W. Whittaker Proposal		
Date of May 1981 Proposal	(Name or Identification of Listing)	(Address or Location)
Suggested CLASSIFIED Category	Bibliography Department of Main Roads Records	Owner and Address Department of Main Roads,
Committee IAC (Trust Use)	Department of Main Roads Pamphlet "Bridges of the Hunter Valley"	309 Castlereagh Street Sydney 2000
Council (Trust Use) 3/5/82	1980	
Description Briefly cover th	e points on the following check list where they are relevant and w	within your knowledge.
Style mid1	Adalam badda da a dashla Daman an M	-111 + + 11

Style
Construction
Use
Architect/s
Builder/s
Date of
Construction
Present
Co- on
His
Owners
Boundaries
of proposed
listing


This early timber bridge is a double Warren or Mcdonald type truss bridge of two spans 30.5 m long. Built in 1878 the bridge rests on an early design of cast iron piers diagonally braced by bolted cast angle sitffeners. The low depth trusses consist of massive square section hardwood baulks held together by vertical iron ties. The bridge has been strengthened by placing cable tension ties below the bottom of the truss chords. In 1927 the bridge trusses were rebuilt to the original design. The approach spans originally of timber, were reinforced with steel girders, the timber beams being removed in 1974.


This bridge is in a good condition and is flanked by one approach span on the western side and 3 approach spans on the eastern side. There are no plans to replace it.

Rott

Reasons for listing

The oldest known timber truss bridge in the care of the NSW Department of Main Roads. As a first stage of the technological development of heavier bridges in the Hunter valley, this bridge is uniquely important in the story of bridges. It is representative of hundreds of bridges that once dotted N.S.W. but which are now becoming rare. Its setting is most attractive surrounded by rural countryside. The town picnic area is nearby. This bridge is an essential component in the evolution of bridges in the Hunter Valley, from timber through iron plate girder, lattice girder, lift span to steel truss bridges such as at Dunolly. Clarencetown bridge also adds magnificantly to an attractive landscape.





DUNGOG HERITA Perumal, Wrathall & Murphy Pty. in association with Cameron McNa	AGE STUDY Ltd. for Dungog Shire Counce mara Heritage Council of NSV	il V	Item A34	Photograph BW 2/22A C 2/16	
Location Dungog, over Will	liams River at Caravan Pa	rk	Precinct Date 17/	1/87	
Title Description Cooreei Bridge Survey By AB					
Description Built by the PWD in 1904 underneath the central s	4. All timber bridge exc section which are steel.	ept f	or the mai	n beams	
History:					
Significance: Regional and local					
Alterations/Integrity:					
Condition: Good Fair Poor	Style: Period: □ Pre-1890 □ 1915-45	Po □ N	et Context: ositive contribute eutral out of Character		
Current Use: Original use: Bridge	☐ 1890-1915 ☐ 1945- Actual date / 9044 (if known)		ible remedies	. 1	
Current listings: ☐ AHC ☐ HC ☐ NT ☐ RAIA/Other					
Thematic context Transport					
References: Thematic History : 105					
*	and the second s				

